

Received 2-28-92

CR CR

WILLIAM G. FULTZ, JR.
Professional Surveyor
819 Lori Court
Sidney, Ohio 45365
(513) 492-9674

BRAUTIGAM DESCRIPTION

Part of Fra. Sec. 36, T3, R13, M.R.S.,
Miami Twp., Logan Co., Ohio:

Beginning at a RR Spike set in the southwest corner of said fractional section 36;

Thence $N00^{\circ}-08'-51''E$, along the west line of said fractional section 36 and the center of County Road No.4, 1452.00 ft. to a RR Spike set in the southwest corner of the Robert Staley property;

Thence $N89^{\circ}-56'-45''E$, along the south line of said Robert Staley property, 3012.24 ft. to a 5/8" rebar set on the west line of the Steven Brautigam property;

Thence $S00^{\circ}-08'-51''W$, along said west line of the Steven Brautigam property, 1452.00 ft. to a concrete corner post found on the south line of said fractional section 36;

Thence $S89^{\circ}-56'-45''W$, along said south line of fractional section 36, 3012.24 ft. to the place of beginning.

Containing 100.407 Ac. more or less, of which 1.000 Ac. are in road right-of-way, being subject to all legal highways and easements of record, and being the same premises recorded in Vol. 340 Pg. 283 of the Logan Co. Deed Records.

This description was prepared by William G. Fultz, Jr. Reg. Surveyor No.5173 on Feb. 22, 1992 and is based on an actual field survey with bearings and distances made by field measurements, basis of bearings $S89^{\circ}-56'-45''W$ on the south line of section 36 is from a survey made by William G. Fultz, Jr. for C. & D. Gibbs located along the north line of section 35 and the south line of section 36.



William G. Fultz, Jr.

William G. Fultz, Jr.
Reg. Surveyor No. 5173

INDEXED ON MAP
8668 1D

BRAUTIGAM SURVEY
 Part of Fra. Sec. 36, T3, R13,
 M.R.S., Miami Twp, Logan Co., Ohio

Robert P. Staley
 100 Ac
 Vol. 301 Pg. 951

N 89° 56' - 45" E
 3012.24'

100.407 Ac.
 1.000 Ac. in R/W
 Gerald R. & Ruth Ann Brautigam
 Vol. 340 Pg. 283

Sec. 36

3012.24'
 S 89° 56' - 45" W Section Line

Sec. 35
 C. & D. Gibbs
 54,084 Ac
 OR 22 Pg. 848

Wm Foster
 14.751 Ac
 OR 27 Pg. 276

Robert Staley
 7 Ac.
 Vol. 197 Pg. 162


INDEXED ON MAP
 8668 IP



Surveyed: 22 Feb, 1992
 William G. Fultz, Jr.
 William G. Fultz, Jr. Reg. Surveyor 5173
 Lori Ct.
 Sidney, Ohio, 45365 Ph. 513-492-9674

The Basis of bearing is the
 South line of Sec. 36 and north
 line of Sec. 35 is from a survey
 made by me for C. & D. Gibbs
 (S 89° 56' - 45" W).

S. & L. Brautigam
 49.903 Ac
 Vol. 382 Pg. 748



1" = 300'

Concrete Corner Post

1452.00'
 S 0° 08' 51" W

5/8" Rebar Set

NW Corner of SW 1/4
 1/2 Sec. Line

RR Spk Set
 60'
 30'

SHELBY COUNTY
 CR NE 4
 Sec. Line
 N 0° 08' 51" E
 1452.00'

RR Spk Set by
 Minimization
 on CR # 4 and
 Road records
 30'
 SW Corner of Sec. 36
 5/8" Rebar Set
 5/8" Rebar found

Corner Stone in
 Mon. Box Ed.
 5/8" Rebar Set