

FB 711

Walnut St.
North Fork Subdivision
Richland Twp., Logan Co., Ohio
Desc.

- Pt.
- A.) $\frac{5}{8}$ " ϕ rebar Fd.
- B.) $\frac{3}{8}$ " ϕ rebar Fd.
- C.) $\frac{5}{8}$ " ϕ rebar Fd.
- D.) $\frac{5}{8}$ " ϕ cpd. rebar Fd. - D.E.G.
- E.) $\frac{5}{8}$ " ϕ rebar Fd.
- F.) $\frac{3}{8}$ " ϕ rebar Fd.
- G.) $\frac{7}{8}$ " ϕ rebar Fd.
- H.) $\frac{5}{8}$ " ϕ rebar Fd.
- I.) $\frac{1}{2}$ " I.D. pipe Fd. (leaner) ?
- J.) $\frac{5}{8}$ " ϕ cpd. rebar Fd. - D.E.G. - Ref. R-8029
- K.) $\frac{5}{8}$ " ϕ cpd. rebar set - we reset this pt.
@ the request of the Indian Lake Sanitary
Sewer Office. They tore this pt. out
while doing some sewer work.
- L.) $\frac{5}{8}$ " ϕ cpd. rebar Fd. - D.E.G. - Ref. R-8029
- M.) $\frac{5}{8}$ " ϕ rebar Fd.
- N.) $\frac{5}{8}$ " ϕ rebar Fd.
- O.) R.R. spl set @ P.C. of curve
- P.) $\frac{5}{8}$ " ϕ rebar Fd. - P.I. of Walnut St.
- Q.) R.R. spl set @ P.T. of curve
- R.) R.R. spl set plat distance (575.97')
from pt. P. on line P-F.

INDEXED ON MAP
7231

C. Nichols
C. Dill
B. Simmons

April 2002

64

