Recieved 11-7.86 OX

William G. Fultz, Jr. & Associates PROFESSIONAL SURVEYOR 1310 Hickory Court Sidney, Ohio 45365

G TBBS DESCRIPTION

2.031 Ac. Tract

Part of Section 35, T3, R13, M.R.S., Miami Twp., Logan Co., Ohio:

Commencing at an iron pin on the west line of said section 35 (C.R.#4) in the center of C.R.#70; thence N88°-45'E, along said center of C.R. #70, 2379.80 ft. to a RR Spike and the place of beginning for the following described real estate:

Thence NO -33'E. 304.00 ft. to a 5/8"x30" reinforcing rod;

Thence $N89^{\circ}$ -20'-15"E, 292.62 ft. to a 5/8"x30" reinforcing rod;

Thence SO -33'W. 301.00 ft. to a RR Spike in the center of said C.R.#70:

Thence S880-45'W, along said center, 292.70 ft. to the place of beginning.

Containing 2.031 Ac. more or less, being subject to all legal highways and easements of record, and being part of the premises recorded in Vol.O.R.22, Pg.848 of the Logan Co. Deed Records.

Starting bearing from prior survey, this description was prepared from a survey made by William G. Fultz, Jr. on October 18, 1986.

William G. Fultz, Jr.

Reg. Surveyor No.5173

William G. Fultz, Jr. & Associates

PROFESSIONAL SURVEYOR

1310 Hickory Court

Sidney, Ohio 45365

GIBBS DESCRIPTION

2.012 Ac. Tract

Part of Section 35, T3, R13, M.R.S., Miami Twp., Logan Co., Ohio:

Commencing at an iron pin on the west line of said section 35 (C.R.#4) in the center of C.R.#70; thence N88°-45'E, along said center of C.R.#70, 2672.50 ft. to a RR Spike and the place of beginning for the following described real estate:

Thence NO°-33'E, 301.00 ft. to a 5/8"x30" reinforcing rod;

Thence N89°-20'-15"E, 292.62 ft. to a 5/8"x30" reinforcing rod;

Thence SO -33'W, 298.00 ft. to a RR Spike in the center of said C.R.#70;

Thence S88°-45'W, 292.70 ft. to the place of beginning.

Containing 2.012 Ac. more or less, being subject to all legal highways and easements of record, and being part of the premises recorded in Vol.O.R.22, Pg.848 of the Logan Co. Deed Records.


Starting bearing from prior survey, this description was prepared from a field survey made by William G. Fultz, Jr. on October 18, 1986.

William G. Fults, Jr. Reg. Surveyor No.5173

INDEXED ON MAP 75.98 ID 2

GIBBS SURVEY
Part of Sec. 35, T3, R13, M.R.S.,
Miami Twp., Logan Co., Ohio

Christopher R. & Deboroh J. Gibbs Vol. ORZZ Pg. 848 54.084 Ac



SURVEYED 18 Oct. 1986

REG. SURVEYOR Nº 5173

INDEXED ON MAP

Received 1-21-87 OK Z.C.P.

William G. Fultz, Jr. & Associates

PROFESSIONAL SURVEYOR 1310 Hickory Court Sidney, Ohio 45365

Christspher

GIBBS DESCRIPTION

10.244 Ac. Tract

Part of Sec. 35, T3, R13, M.R.S., Miami Twp., Logan Co., Ohio:

Commencing at an iron pin found on the west line of said section 35 (C.R.#4) in the center of C.R.#70; thence N88°-45'E, along said center of C.R.#70, 1562.75 ft. to a RR Spike found on the east line of the premises recorded in O.R. Vol.27 Pg.276, and the place of beginning for the following described real estate:

Thence N4°-Ol'-15"W, along said east line, 524.21 ft. to a 5/8"x30" rebar set;

Thence N87°-35'-30"E, 859.57 ft. to a 5/8"x30" rebar set;

Thence SO^{0} -33'W, 541.25 ft. to a RR Spike found in the center of C.R.#70;

Thence S88°-45'W, along said center of C.R.#70, 817.05 ft. to the place of beginning.

Containing 10.244 Ac. more or less, being subject to all legal highways and easements of record, and being part of the premises recorded in O.R. Vol. 22 Pg.848 of the Logan Co. Deed Records.

This description was prepared by William G. Fultz, Jr. Reg. Surveyor No.5173 on Jan.10, 1987 based on a field survey, bearings and distances from field measurements, bearings based on centerline bearing of C.R.#70.

Bearing of C. R. 70 boing

- 1

William G. Fultz, Jr. Reg. Surveyor No.5173

INDEXED ON MAP 7598 2D

