

# Road # 38

10-19-44  
Dysert  
Dickinson  
R. Wilgus

To locate Corners of

V.M.S. 12278<sup>2</sup> - 10503 to 9969  
12311<sup>5</sup>

Found 2- 2"x2" Hubs in Fence line  
on S. side of road #38. See Field Book  
642 page 23 (By Scott)

Set sight stakes 15' N. of R.W. Mon.  
at Sta. 2400 and 3200 and checked  
line as found by measurements  
from 2"x2" Hubs - O.K.

From R.W. Mon. at Sta. 2400 to point  
248'

From Sta. 3200 to point 562'

From Wickersham Fence to point 140.2'  
Could Not Find old stone.

Place concrete R.W. Mon. in place of  
old stone 4" below berm with broken  
pieces of tile

Replaced 2"x2" Hubs with  $\frac{3}{4}$ " x 24"  $\phi$  Irons

