


- SYMBOLS:
- - P. K. Nail in Concrete Driveway Fd.
 - ⊗ - 5/8" Rebars in 1 1/2" Iron Pipes Fd.
 - - 5/8" x 30" Rebars Set.

INDEXED ON MAP
9200 1P



| | | |
|---|--------------|----------------------------------|
| Hanna-Jenson Survey Lot No. 46-82, Section No. 36, Town 6, Range 8, Village of Russells Point, Washington Township, Logan County, Ohio. | | |
| SCALE 1" = 20' | APPROVED BY: | DRAWN BY DEG |
| DATE 8-3-1999 | | REVISED |
| Daniel E. Gilbert, P.S. Daniel E. Gilbert, P.S. Reg. Sur. No. 5402 | | DRAWING NUMBER 099-034 |

2/2
Revised 6-9-00 by gca



LEGEND

- ⊕ 3/4 INCH SQUARE IRON ROD FOUND
- ⊗ 5/8 INCH IRON ROD FOUND IN A 2 INCH IRON PIPE
- 5/8 INCH IRON ROD FOUND

RETRACEMENT SURVEY OF THE
 THOMAS C. GRUNDISH
 LOT 46-86 OF
 INDIAN LAKE RESERVOIR LANDS
 PLAT CABINET A. SLIDE 431
 VILLAGE OF RUSSELLS POINT
 SECTION 36, TOWN 6, RANGE 8
 WASHINGTON TOWNSHIP
 LOGAN COUNTY, OHIO



SURVEYED BY:
William K. Bruce
 WILLIAM K. BRUCE
 PROFESSIONAL SURVEYOR 7437
 MAY 10, 2000

COPYRIGHT 2000 BY:
LEE SURVEYING & MAPPING CO., INC.
 117 North Madriver Street
 BELLEFONTAINE, OHIO 43311
 (937) 593-7335

2 WORKING DAYS
BEFORE YOU DIG
 CALL TOLL FREE **800-362-2764**
 OHIO UTILITIES PROTECTION SERVICE.

INDEXED ON MAP
 9280 2P

ORIGINAL STAMP IN GREEN