

Stone Found

MARLIN JACK DAINES
71.5 AC.

DEEP ANGLE
61° 00'

S. 87° 17' E.

226.2'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

242.5'

S. 2° 13' W.

163.6'

N. 13° 16' E. 297.0'

10" x 10" CONCRETE POST

10" x 10" CONCRETE POST

MONROE TOWNSHIP TRUSTEES
1.26 AC.

KENNETH F. WENGER ETUX
1/30 O.A.C.

V.M.S. 2878
" 10107
" 10718
" 10714

8" GALVANIZED DR.

ROBERT D. GODWIN
44.41 AC.

TOWNSHIP ROAD No. 1974

EXIST. PAVEMENT

STONE FOUNDATION

5" SQUARE STONE FOUND
0.3' NORTH AND 0.8' EAST
OF 1/2" IRON BAR

S. 77° 00' W. 82.5'

168.0'

99.99.0'

N. 72° 16' W.

137.6'

153.3'

S. 7° 07' W.

108.5'

V.M.S. LINE

SCALE 1" = 20'
● = 1" IRON BAR SET
--- = EXISTING FENCE

SURVEY
OF
MACACHEEK CEMETERY
V.M.S. 10091
MONROE TOWNSHIP
LOGAN COUNTY, OHIO
CHESTER P. KUERTZ, P.E.
COUNTY ENGINEER

SURVEYED BY D.L. DODSON 12/9/71
DRAWN BY L.H. GESSNER 12/16/71