

INDIAN LAKE

Donald E. Erb, Jr. et ux  
O. R. No. 355 P. 455 (2-25-1998)  
43-006-13-12-004.000  
0.046 Acres  
First Tract

Pam S. Leach et al  
O. R. No. 397 P. 803 (1-26-1999)  
43-006-13-12-005.000  
3,604.580<sup>sq</sup> or 0.083 Acres

Charles Yager et ux  
D. Vol. No. 393 P. 408 (5-26-1981)  
43-006-13-12-006.000  
0.070 Acres  
First Tract

43-006-13-12-004.001  
0.0170 Acres  
Second Tract


Lot No. 46-414  
43-006-13-12-005.001  
1,515.220<sup>sq</sup> or 0.035 Acres

43-006-13-12-006.001  
0.0430 Acres  
Second Tract


Note: This line established by survey and record in July, 1965 by Owen K. Shirk, Reg. Sur. No. 4271, 38.32'

Chisel Mark on Con. Seawall Fd.

- Symbols:
- - 5/8" Rebar Fd.
  - - 3/4" O. D. Iron Pipes Fd.
  - ⊗ - 3/4" Round Iron Bar Fd.



Scale: 1" = 10'



LEACH SURVEY - V.M.S. No. 12277  
Turkeyfoot Point, Stokes Township,  
Logan County, Ohio.

SCALE: 1" = 10'	APPROVED BY:	DRAWN BY: DEG
DATE: 1-28-1999		REVISED:
Daniel E. Gilbert, P.S. Daniel E. Gilbert, P.S. Reg. Sur. No. 5402		DRAWING NUMBER: 099-002

INDEXED ON MAP  
4207

S-495

PARK ST. - 20'  
Basis of Bearing  
S. 40°-24'-00" W.

