



Surveyed for Partition Commissioners,
Martin Miller, Henry McKinnon and
Daniel W. Koch.

S. E. Qr. Sec. 31, ½ S. E. Qr. Sec. 32, T. 3, R. 14,
Pleasant Tp. ½ West ½ of N. W. Qr. Sec. 30,
T. 4, R. 13, Union Tp. Surveyed 14, 15 ½ 19, June 1907.

~Description of Corners~

- A - Stone, with five empty bottles.
- B - Stone 4ft. north of center of gravel on Degraff pike.
- C - Stone - Wit: Fence post 9 lks. north ¾ 12" Apple tree 18" S.E.
- D - Stone - Wit: 4" Peach tree 2ft. east ½ 5" Apple tree 22 lks. S.E.
- E - Stone - 8" square on top, with pieces of drain tile.

O. C. Richey }
W. H. Tamplin } Chain Cr.
H. J. Tamplin }

Herbert Tamplin }
Harry Castle } Flagman



Scale: 1 in. = 10 chains

Charles M. Richey
County Surveyor